

- 1. A collaborative and committed plan for the next 5 days.
- 2. Only plan ready work.
- 3. Measure, learn and improve with a goal of 100% reliability.
- 4. Make it visual and easy to understand.



- 1. A collaborative and committed plan for the next 5 days.
- 2. Only plan ready work.
- 3. Measure, learn and improve with a goal of 100% reliability.
- 4. Make it visual and easy to understand.



- 1. A collaborative and committed plan for the next 5 days.
- 2. Only plan ready work.
- 3. Measure, learn and improve with a goal of 100% reliability.
- 4. Make it visual and easy to understand.



- 1. A collaborative and committed plan for the next 5 days.
- 2. Only plan ready work.
- 3. Measure, learn and improve with a goal of 100% reliability.
- 4. Make it visual and easy to understand.